# UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO. : 6,755,500 B2 DATED : June 29, 2004 INVENTOR(S) : Hirano et al. Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### Column 1,

Line 66, "Laying-open" should read -- Laid-open --.

### Column 3.

Line 2, "connected" should read -- connected to --; Line 62, "rectangular," should read -- rectangle, --; and Line 63, "rectangular" should read -- rectangle, --.

### Column 4,

Line 61, "objet" should read -- object --.

#### Column 6.

Line 58, "inkjet" should read -- ink-jet --.

#### Column 11,

Line 61. "2M" should read -- 2OM, --.

#### Column 12

Line 9, "independent" should read -- independent of --.

## Column 13,

Line 4, "bug" should read -- bung --; and Line 9, "2 le" should read -- 21e --.

#### Column 15.

Line 18, "311" should read -- 31i --; Line 31, "6n" should read -- on --; and

# Line 38, "311." should read -- 31i. --.

## Column 16,

Line 13, "automatically" should read -- automatic --; and Line 44, "rotate" should read -- rotations --.

## Column 18,

Line 64, "form" should read -- from --.

### Column 19.

Line 19, "formed" should read -- formed by --;

Line 21, "communicates" should read -- communicates with --; and

Line 57, "simple." should read -- simply --.

# UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO. : 6,755,500 B2 : June 29, 2004 Page 2 of 3

DATED INVENTOR(S) : Hirano et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Lines 21 and 27, "varyingly" should read -- varied --.

Column 21.

Line 18, "detect" should read -- detects --; and Line 45, "form" should read -- from --.

Column 22, Line 33, "fifth" should read -- sixth --; and

Column 25,

Line 6, "shown" should read -- shown in --.

Column 26,

Line 11, "s" should read -- is --.

Line 33, "detect" should read -- detects --; and Line 62, "currently" should read -- currently in --.

Line 26, "synthesis" should read -- synthetic --;

Line 38, "tryfluoromethyl" should read -- trifluoromethyl --; and

Line 50, "These" should read -- This --.

Column 31.

Line 5, "nozzles" should read -- nozzle --;

Line 39, "501M, 501M," should read -- 501M, 501Y, --;

Line 43, "but ink." should read -- but not ink. --; and

Line 47, "ale" should read -- able --.

Column 33. Line 8, "shown" should read -- shown in --;

Line 21, "conditions." should read -- condition --;

Line 23, "view" should read -- views --; and

Line 41, "a" should read -- an --.

Column 34,

Line 8. "in" should read -- in the --; and

Line 66, "i.e.," should read -- (i.e., --.

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,755,500 B2 DATED : June 29, 2004

Page 3 of 3

INVENTOR(S) : Hirano et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### Column 35,

Line 5, "medium" should read -- medium. --; and Line 13, "but ink." should read -- but not ink. --.

#### Column 36.

Line 13, "prevents" should read -- prevent --; Line 49, "configures" should read -- configured --; and Line 61, "filed" should read -- filled --.

#### Column 37.

Line 7, "in Figure." should read -- in the Figure. --; Line 29, "fist" should read -- first --; Line 34, "to fitted" should read -- to be fitted --; Line 59, "10g" should read -- log --; and Line 64, "seating" should read -- seating --.

## Column 38.

Line 15, "need-like" should read -- needle-like --; and Line 64, "twentieth" should read -- twenty-first --.

#### Column 39.

Lines 1 and 6, "twentieth" should read -- twenty-first --; Line 22, "an" should read -- a --; and Line 25, "synthesis" should read -- synthetic --.

Signed and Sealed this

Fourteenth Day of December, 2004

Jon W. Dudas

JON W. DUDAS
Director of the United States Patent and Trademark Office